

M.K.D

PATENT Attorney Matter No. 3382-53696-01

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Zintel et al.

Date Mailed July 27, 2004

Certificate

AUG 0 4 2004

of Correction

Patent No. 6,725,281 **b**(**Issued:** April 20, 2004

Application No. 09/432,853

Filed: November 2, 1999 Confirmation No. 1670

For: SYNCHRONIZATION OF CONTROLLED

DEVICE STATE USING STATE TABLE AND EVENTING IN DATA-DRIVEN REMOTE DEVICE CONTROL MODELS

Examiner: Viet D. Vu

Art Unit: 2154

Attorney Reference No. 3382-53696-01

COMMISSIONER FOR PATENTS P.O. BOX 1450 ALEXANDRIA, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In the Specification:

Column 1, line 31, "move-digital" should read --move digital--, as shown on page 1, line 21 of the Application.

Column 2, line 48, "Additional," should read --Additional--, as shown on page 3, line 8 of the Application.

Column 6, line 31, "interface this" should read --interface. This--, as shown on page 11, line 25 of the Application.

Column 7, line 19, "AN" should read --A/V--, as shown on page 13, line 17 of the Application.

Column 9, line 57, "ssdp-v 1-02.txt" should read --ssdp-v1-02.txt--, as shown on page 18, line 24 of the Application.

Column 16, line 30, "19941 105T08:1" should read --19941105T08:1--, as shown in the Table on page 33, in the Application.

Column 16, line 31, "5:5 +03" should read --5:5+03--, as shown in the Table on page 33, in the Application.

Column 18, line 5, title of table "UPnP Addresses" is not shown in the Patent, as shown on page 37, line 1 of the Application.

Column 18, line 30, title of table "UPnP SSDP Level Searches and Results" is not shown in the Patent, as shown on page 38, line 6 of the Application.

Column 19, line 18, "the. Device" should read -- the Device--, as shown on page 40, line 3 of the Application.

Column 19, line 25, title of table "UPnP SSDP Announcements" is not shown in the Patent, as shown on page 40, line 7 of the Application.

Column 19, line 26, "Notofication" should read --Notification--, as shown on page 40, line 8 of the Application.

Column 19, line 52, "XML.document" should read --XML document--, as shown on page 41, line 8 of the Application.

Column 21, line 67, "Obect" should read --Object--, as shown on page 45, line 26 of the Application.

Column 27, line 62, "<argument>element" should read --<argument> element--, as shown on page 57, line 9 of the Application.

Column 29, line 14, "SSBP" should read --SSDP--, as shown on page 60, line 3 of the Application.

Column 30, line 62, "put Event Handler" should read --put_EventHandler--, as shown on page 63, line 14 of the Application.

Column 32, line 19, "Erroro" should read --Error()--, as shown on page 66, line 3 of the Application.

Column 42, line 5, "v. Write the </prop> closing tag" should be indented one tab, as shown on page 84, line 16 of the Application.

Column 51, line 12, "modem 101 2" should read --modem 1012--, as shown on page 102, line 18 of the Application.

Column 51, line 18, "printer 101 5" should read --printer 1015--, as shown on page 102, line 23 of the Application.

All of the above errors are attributable to the Patent Office. A Certificate of Correction is enclosed in duplicate to make formal notice of the errors in the referenced patent.


Respectfully submitted,

KLARQUIST SPARKMAN, LLP

Stephen A. Wight
Registration No. 37,759

One World Trade Center, Suite 1600 121 S.W. Salmon Street Portland, Oregon 97204

Telephone: (503) 226-7391 Facsimile: (503) 228-9446



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Zintel et al.

Date Mailed July 27, 2004

Patent No. 6,725,281 **(b) Issued:** April 20, 2004

Application No. 09/432,853 **Filed:** November 2, 1999 **Confirmation No.** 1670

For: SYNCHRONIZATION OF CONTROLLED

DEVICE STATE USING STATE TABLE AND EVENTING IN DATA-DRIVEN REMOTE DEVICE CONTROL MODELS

Examiner: Viet D. Vu

Art Unit: 2154

Attorney Reference No. 3382-53696-01

COMMISSIONER FOR PATENTS P.O. BOX 1450 ALEXANDRIA, VA 22313-1450

LETTER OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In the Specification:

Column 1, line 19, "environment" should read --environment.--.

Column 3, lines 42-43, "FIG. 25" should read --FIG. 25.--

Column 5, lines 25-26, "maintains and a persistent" should read --maintains a persistent--.

Column 5, line 37, "Protocols" should read -- Protocol--.

Column 5, line 57, "accomplishing" should read --accomplished--.

Column 7, line 21, "complaint" should read --compliant--.

Column 7, line 61, "of minimum version" should read -- of a minimum version--.

Column 8, line 59, "remotes are" should read --remotes, are--.

Column 10, line 34, "than" should read --that--.

Column 10, line 52, "Java Applet" should read -- Java Applet--.

Column 10, line 65, "than" should read --that--.

Column 12, line 26, "is a follows:" should read -- is as follows:--.

Column 14, line 9, "SST published" should read --SST is published--.

Column 15, line 5, "in controlled" should read --in a controlled--.

Column 15, line 6, "must be proper superset" should read --must be a proper superset--.

Column 15, line 28, "is cohesive" should read -- is a cohesive--.

Column 15, line 31, "Devices" should read -- Devices, --.

Column 15, line 40, "that minimal" should read --that a minimal--.

Column 16, line 13, "Value" should read -- Value.--.

Column 16, line 47, "to current" should read -- the current--.

Column 17, line 2, "an device" should read --a device--.

Column 17, lines 50-51, "by Controlled" should read --by the Controlled--.

Column 18, line 22, "SUBSCIBE" should read -- SUBSCRIBE ---.

Column 22, line 10, "addition to the creating" should read --addition to creating--.

Column 22, line 50, "is" should read --its--.

Column 25, line 5, "URLS" should read -- URLs--.

Column 27, line 15, "associated the" should read --associated with the--.

Column 27, line 46, "<serviceState Table>" should read --<serviceStateTable>--.

Column 28, line 30, "subsystem is" should read --subsystem's--.

Column 31, line 8, "The handles" should read -- This handles--.

Column 33, lines 28-29, "[in] Unused." should read --[in] is unused.--.

Column 33, line 32, "message" should read --message.--.

Column 33, line 53, "as" should read --a--.

Column 36, line 47, "that is has" should read --that it has--.

Column 38, line 23, "The XML will be contains" should read -- The XML contains--.

Column 38, line 37, "O.k." should read --O.K.--.

Column 38, line 60, "session" should read --session.--.

Column 39, line 6, "requests" should read --requests.--.

Column 40, line 6, ""Subscription-Id"" should read -- "Subscription-ID" ---

Column 40, line 67, "structure" should read --structure.--.

Column 42, line 6, "tag" should read --tag.--.

Column 42, line 7, "tag" should read --tag.--.

Column 42, line 14, "HttpEndRequest()" should read --HttpSendRequest()--.

Column 42, line 66, "UCPs" should read --UCP's--.

Column 43, line 2, "in" should read --it--.

Column 44, line 18, "optical drive" should read --optical disk drive--.

Column 49, line 4, "modules" should read --module--.

Column 51, line 43, "network" should read --networks--.

The above errors are not attributable to the Patent Office, but they are not considered to be of major significance. Applicants request that this document be included in the file wrapper of the subject patent to make formal notice of the errors.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

Stephen A Wigh

Registration No. 37,759

One World Trade Center, Suite 1600 121 S.W. Salmon Street

Portland, Oregon 97204

Telephone: (503) 226-7391 Facsimile: (503) 228-9446

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,725,281 B1

DATED : April 20, 2004

INVENTOR(S) : Zintel et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 31, "move-digital" should read -- move digital --

Column 2.

Line 48, "Additional," should read -- Additional --

Column 6.

Line 31, "interface this" should read -- interface. This --

Column 7,

Line 19, "AN" should read -- A/V --

Column 9,

Line 57, "ssdp-v 1-02.txt" should read -- ssdp-v1-02.txt --

Column 16,

Line 30, "19941 105T08:1" should read -- 19941105T08:1 --

Line 31, "5:5 +03" should read -- 5:5+03 --

Column 18,

Line 5, title of table "UPnP Addresses" is not shown in the Patent Line 30, title of table "UPnP SSDP Level Searches and Results" is not shown in the Patent

Column 19,

Line 18, "the. Device" should read -- the Device --

Line 25, title of table "UPnP SSDP Announcements" is not shown in the Patent

Line 26, "Notofication" should read -- Notification --,

Line 52, "XML.document" should read -- XML document --

Column 21,

Line 67, "Obect" should read -- Object --

Column 27,

Line 62, "<argument>element" should read -- <argument>element --

Column 29,

Line 14, "SSBP" should read -- SSDP --

Column 30.

Line 62, "put Event Handler" should read -- put EventHandler --

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,725,281 B1

: April 20, 2004

Page 2 of 2

DATED INVENTOR(S) : Zintel et al.

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 32,

Line 19, "Erroro" should read -- Error() --

Line 5, "v. Write the </prop> closing tag" should be indented one tab

Column 51,

Line 12, "modem 101 2" should read -- modem 1012 --

Line 18, "printer 101 5" should read -- printer 1015 --

Signed and Sealed this

Fourteenth Day of September, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,725,281(6)

DATED : April 20, 2004

INVENTOR(S) : Zintel et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 1, line 31, "move-digital" should read --move digital--, as shown on page 1, line 21 of the Application.

Column 2, line 48, "Additional," should read --Additional--, as shown on page 3, line 8 of the Application.

Column 6, line 31, "interface this" should read --interface. This--, as shown on page 11, line 25 of the Application.

Column 7, line 19, "AN" should read --A/V--, as shown on page 13, line 17 of the Application.

Column 9, line 57, "ssdp-v 1-02.txt" should read --ssdp-v1-02.txt--, as shown on page 18, line 24 of the Application.

Column 16, line 30, "19941 105T08:1" should read --19941105T08:1--, as shown in the Table on page 33, in the Application.

Column 16, line 31, "5:5 +03" should read --5:5+03--, as shown in the Table on page 33, in the Application.

Column 18, line 5, title of table "UPnP Addresses" is not shown in the Patent, as shown on page 37, line 1 of the Application.

Column 18, line 30, title of table "UPnP SSDP Level Searches and Results" is not shown in the Patent, as shown on page 38, line 6 of the Application.

Column 19, line 18, "the. Device" should read -- the Device--, as shown on page 40, line 3 of the Application.

Column 19, line 25, title of table "UPnP SSDP Announcements" is not shown in the Patent, as shown on page 40, line 7 of the Application.

Column 19, line 26, "Notofication" should read --Notification--, as shown on page 40, line 8 of the Application.

MAILING ADDRESS OF SENDER:

Klarquist Sparkman, LLP One World Trade Center, Suite 1600 121 SW Salmon Street Portland, Oregon 97204 PATENT NO. 6,725,2816 No. of add'l copies (@ .30 per page)

Column 19, line 52, "XML.document" should read --XML document--, as shown on page 41, line 8 of the Application.

Column 21, line 67, "Obect" should read --Object--, as shown on page 45, line 26 of the Application.

Column 27, line 62, "<argument>element" should read --<argument> element--, as shown on page 57, line 9 of the Application.

Column 29, line 14, "SSBP" should read --SSDP--, as shown on page 60, line 3 of the Application.

Column 30, line 62, "put Event Handler" should read --put_EventHandler--, as shown on page 63, line 14 of the Application.

Column 32, line 19, "Erroro" should read --Error()--, as shown on page 66, line 3 of the Application.

Column 42, line 5, "v. Write the </prop> closing tag" should be indented one tab, as shown on page 84, line 16 of the Application.

Column 51, line 12, "modem 101 2" should read --modem 1012--, as shown on page 102, line 18 of the Application.

Column 51, line 18, "printer 101 5" should read --printer 1015--, as shown on page 102, line 23 of the Application.

MAILING ADDRESS OF SENDER: Klarquist Sparkman, LLP One World Trade Center, Suite 1600 121 SW Salmon Street Portland, Oregon 97204 PATENT NO. 6,725,281 B No. of add'l copies (@ .30 per page)